

## Torque Tech - Buick

## Item Listing

February 8, 2010

Item	Qu...	Price	Description
f		0.00	s/h
f Item84		0.00	30 30 16.90 18.10 19.00  20.80  24.30 27.20 30.90   70.80 70.80 82.10
Payment		0.00	...08847251000
BRG350M.010	0	25.00	M77 MS1457P .010 350/340 Main Bearings .010"-- Set
BRG350MFStd	3	28.00	M77 350/340 Full Groove Main Bearings - Std --- Set
BRG350MStd	2	25.00	M77 MS1457P Std 350/340 Main Bearings Std. -- Set
BRG350R.010	2	25.00	M77610P .010 350/340 Rod Bearings -- Set
BRG350R.010 FM	3	25.00	350/340 Rod Brngs .010" Federal Mogul/Sealed Power - Set
BRG455M .020	1	30.00	400-455 Main Bearings .020" - Set M77 MS908P .020
BRG455R .001	2	25.00	455 Rod Bearings .001 Set M/77 CB762P .001
BRG455R .030	1	25.00	400-455 Rod Barings .030" -- Set M77 CB762P .030 - Set
BRGV6RStd	2	14.00	Buick T/V6 Rod Bearings Std. Sealed Power - set
CAM2001	5	3.50	400-455 Cam Change Gasket Set - Fel Pro
CAM2002	1	3.50	350, T/V6 Cam Change Gasket Set - Fel Pro
CAMSP22	2	90.00	SP 22 -- Buick 350 Cam 235/245 .508"/.527" 112LS 4 Deg Advance - ea
CAMSP8S	1	90.00	SP 8S -- Buick 455 Solid Cam 274/284 .566"/.566" 108LS No Advance
FP350B	2	5.00	340/350 Brass Freeze Plug Kit - Less Cam Bearing Plug
FP350S	6	2.00	340/350 Steel Freeze Plug Kit - Less Rear Cam Bearing Plug
FP455B	3	5.00	400,430,455 Brass Freeze Plug Kit - Less Rear Cam Bearing Plug
GAS252FullSet	1	30.00	Buick 252 Full Set Gasket Set Fel Pro - Set
GAS350FS1	1	20.00	Buick 350 Full Set - less valve cover set - no Valley Pan
GAS350FS2	1	13.00	Buick 350 Full Set - less valve cover set & less Head Gaskets - No Valley Pan
GAS350OP	5	3.00	Buick 350 Oil Pan Gasket Set - ea Fel Pro
GAS350VC	0	4.00	Buick 350/340 Valve Cover Gasket Set FEL VS50034R
GAS350WP	8	1.50	Buick 350/T/V6 Water Pump Gasket - Fel Pro - ea
GAS455HDR	24	4.00	Buick 400-455 Header Gaskets - ea
GAS455OilPump	23	0.70	Buick 400-455 Oil Pump Gasket Fel Pro - ea
GAS455VP72up	4	11.00	Buick 455 Intake Valleypan '72 Up Fel Pro
GAS455WP	16	1.50	Buick 400-455 Water Pump Gasket Fel Pro - ea
GASFuelPump	27	0.75	Buick Fuel Pump Gasket 400-455, 350, Fel Pro - ea
HBSV6Stg1	3	15.00	Buick V6 Stage 1 Head Bolt Kit ARP 123-3601
HBSV6Stock	1	20.00	Buick T/V6 Stock "Tork to Yield" Head Bolts - Set
HBSV6Stock E	1	9.00	Buick T/V6 Stock "Tork to Yield" Head Bolts - Set of 11
IGN2Q71	3	40.00	Packard "Dated" Repr Customer cut Spark Plug Wires for 455 2Q71
IGN455DistGear	3	22.00	400-455 Bronze Distributor Gear - ea
IGN4Q70	2	40.00	Packard "Dated" Repr Customer cut Spark Plug Wires for 455 4Q70
IGNDist	5	20.00	Buick 400-455, 350 Distributor (Reconditioned) - No Gear, Cap or Rotor -- ea
LIF455C	3	55.00	Buick 455, 350 Competition Lifters - set
LIF455HV	1	35.00	Buick 455, 350 Hi-Vac Lifters
MBSV6Stg2	1	15.00	Buick V6 Stage 1 and 2 Main Stud Kit (2-Bolt Main) ARP 123-5401 - Set
OIL350Std	2	11.00	Buick 350/340 Standard Oil Pump Kit - ea Melling
OIL455Std	3	11.00	Buick 400-455 Standard Oil Pump Kit Melling
PISV6Std	1	85.00	Buick T/V6 Hypereutectic Pistons Std. Federal Mogul -- Set
PRD350CM	2	22.00	Buick 350 5/16" Chrome Moly Push Rod Set
PRD350CM E	15	1.50	Buick 350 CM 5/16" Push Rod - EA
PRD350CMAdj	1	90.00	Buick 350 5/16" Chrome Moly Adjustable Push Rods w/ Instructions - Set
PRD455CM	2	70.00	Buick 455 5/16" CM 455 Stock Length - Set
PRD455CM E	13	3.00	Buick 455 5/16" Chrome Moly Push Rod - Stock Length -- ea
PRDV6 CM	6	2.00	Buick T/V6 5/16 Chrome Moly Push Rods - Stock Length - ea
RAAArmL 72up	21	3.00	Buick 455, 350, T/V6 Left Rocker Arm - ea
RAAArmR 72up	31	3.00	Buick 455, 350, T/V6 Right Rocker Arm - ea
RAARetainers	81	0.60	Buick Rocker Arm Retainers - 400-455, 350, T/V6 -- ea
RAATV6Shaft	2	4.50	Buick V6 Rocker Shafts - Sold as pair only
RAD160V8	2	8.00	160 Degree Thermostat w/o Gasket all V8, V6 thru '85 -- ea
RAD350 68-70	1	25.00	Buick 350 '68-70 Water Pump - ea
RDB455Stock E	1	25.00	455 Stock GM Rod Bolts - Set of 15
RDBV6Comp-Sho	1	13.00	Buick V6 ARP 123-6001 1.50" UHL Short for T/V6 -- set
RDBV6Stock	3	22.00	Buick T/V6 Stock Rod Bolts GM - Set
RDBV6Stock E	1	15.00	Buick T/V6 Stock Rod Botls - GM -- Set of 8
RNG350M Std	1	30.00	Buick 350 Moly Rings Standard - Sealed Power -- Set
RNG455M .030	1	50.00	Buick 455 Moly Rings .030" Sealed Power -- Set
RNG455M .040	1	30.00	Buick 455 Moly Rings .040" Sealed Power - Set
RNG455PM .035	1	99.00	Buick 455 Moly Rings Std. Sealed Power -- Set
RNG455PM .043	2	85.00	Buick 455 .043" Plasma Moly File Fit 5/64" Rings Speed Pro -- Set
RNGV6M Std	1	30.00	Buick T/V6 Moly Rings - Std. Sealed Power -- Set
RNGV6M Std E	1	3.00	Buick T/V6 Moly Rings -- Std. Sealed Power - 1 Ring Set for 1 Piston
TCH350 CH	1	15.00	Buick 350 Double Roller Timing Chain ONLY - ea
TCH350B Std	1	60.00	Buick 350, 340 Brute Std Timing Set

10:54 AM

02/08/10

**Torque Tech - Buick  
Item Listing  
February 8, 2010**

<u>Item</u>	<u>Qu...</u>	<u>Price</u>	<u>Description</u>
TCH350G Std	3	20.00	Buick 350/340 Brute Lower Gear
TCH455 CH	3	16.00	Buick 400-455 Double Roller Cahin Only - ea
TCH455B 008	1	85.00	Buck 400-455 Brute .008" Timing Set
VAL455Exh	5	5.00	455 Stage 1 Stock Exhaust Valve - ea..S/P V1977
VAL455Int	21	5.00	455 Stock Stage 1 Intake Valve - ea S/P V1922
VALV6Exh SS Exh	3	3.00	Buick T/V6 SS Stage 1 Exhaust Valve - Ea
VALV6Int SS Intake	2	3.00	Buick T/V6 Stage 1 Stainless Steel Intake Valves - ea
BuickCat		0.00	Exhaust Catalog w/Buick Parts Clearance Listing
Misc		0.00	



10:54 AM

02/08/10

**Torque Tech - Buick**  
**Item Listing**  
February 8, 2010

<u>Type</u>	<u>Cost</u>	<u>Sa...</u>	<u>Qu...</u>	<u>Reor...</u>	<u>Qu</u>	<u>Pref...</u>
Inventory P...	0.00		0		0	House
Inventory P...	0.00		0		0	House
Inventory P...	0.00		0		0	House
Inventory P...	0.00		0		0	House
Inventory P...	0.00		0		0	House
Inventory P...	0.00		0		0	House
Inventory P...	0.00		0		0	House
Non-invent...	0					
Non-invent...	0					